

- Notes:
- Survey Grid origin & orientation are related to OS digital data using best fit method.
 - Location of any underground drainage shown is not proven by dye test or other means.
 - Levels are related to Bench Mark located on pier to left of South East entrance of Cathedral. Value 85.91m.
 - Notation:
 w - window opening
 d - door opening
 C - cell level
 Cp - ceiling level
 Sp - level to arch spring point
 H - head level to door / window
 r - window / door recess bricked up
 I.C. - drainage inspection chamber
 G - drainage gully
 r.e. - robbing eye
 d.k. - drop kerb
 rwp - rain water pipe
 rwc - rain water channel
 wsv - water stop valve
 S - Sillard (illuminated)
 EP - electricity / B.T. post

